

Cross-sectional view
of moulding in
correct position.

FIGURE 4

Install glass panel starting as illustrated. Glass is to be inserted in correct groove of moulding as shown in pop-up.




FIGURE 5

Carefully work glass into groove of moulding with the assistance of a small screw driver. Note: The use of safety glasses or goggles is recommended during this operation.